

February 28, 1977

Robert Osmundsen, Enforcement

mm
Monte M. Mienkerk, Land TSS

Kane County - Montgomery/Phillips (Thom) - 08905501

It appears that monitor well number four (southeast corner of site) has an obstruction at about fourteen feet and thus cannot be sampled. In a memo dated November 19, 1976 from Henry Cobo, he stated that the well was installed to a depth of nineteen feet. In a letter to D & N Trucking Company, dated February 17, 1977, from Engineering Enterprises, Inc., of Elburn, Illinois, it is stated that the depth of well number four was only 14.29 feet. On February 22, 1977, I contacted Mr. James K. Michels of Engineering Enterprises, Inc., to confirm that his well number four is the same as the number four well indicated by Henry. Mr. Michels said his number four well is located in the southeast corner of the site, the same location as Henry's number four well.

Henry indicated in his November 14 memo that the water level in well number four was at fourteen feet. If there is now an obstruction in this well, it is very probable that it is above the water table, thus making it impossible to monitor the ground water at this point. Since preliminary indications show a high potential for ground water pollution at this site, it is imperative that the problem with this well be corrected as soon as possible. D & N Trucking can either (1) remove the obstruction and make sure the well is functioning properly, or (2) have the well replaced.

MM:er/FL5

cc: Division File
Northern Region ✓
Dale Montgomery
Tom Clark

RECEIVED

MAR 01 1977

ILL. E.P.A. - D.L.P.C.
STATE OF ILLINOIS

